

## Tree Lighting Installation Instruction











The appearance of packing




Open the packing



Tool fittings inside

<p><b>1:</b> Fix the pole on the ground by foundation screw. (as the picture)</p> 	<p><b>2:</b>Combine the power-line of the branch with the power-line of the pole, and then insert the branch into the interface (as the picture)</p> 
<p><b>3:</b>Tighten the screw by large-size hexagonal spoon,then install all the branch on the same method. (as the picture)</p> 	<p><b>4:</b>Grasp the spray by right hand firmly,then draw the forks by left hand for the optimal appearance. (as the picture)</p> 
<p><b>5:</b>Insert spray into the interface of the branch. (as the picture)</p> 	<p><b>6:</b>Tighten the screw by small-size hexagonal spoon,then install all the sprays on the basis of the same method . (as the picture)</p> 
<p><b>7:</b>Combine the power-line of spray with the power-line of the branch. (as the picture)</p> 	<p><b>8:</b>Check the screws are tightened and the power-lines are combined correctly after all installations.Then turn on the light through current. The installations are finished. (as the picture)</p> 

## Foundation of the installation drawing :



## Installation notes :

Considering security ,some basic preventive measures should be consistently observed during installation and maintenance process ,in order to avoid fire disaster ,electric shock and risks of personal injury .

These preventive measures include the following points:

1. Do not install power lines during thunder and lighting storm.
2. Do not install power source in the water .
3. In any case ,all involved in product installation ,modification ,should be done before the power cut . Switch on the power supply after the completion of all work .